

# ARMOUR - TRUCK



- The Client:** Commercial vehicle manufacturer / repairer.
- The Problem:** Truck beds on tipper lorries becoming damaged and worn through abrasive and corrosive action.
- The Solution:** **Armour - Truck** polyurea elastomer applied direct to steel truck bed as a liner to protect from abrasion and impact damage. A one-coat application at 1mm thickness was sufficient.
- The Outcome:** The truck was repaired and coated within half a day ensuring the company can operate a "same day" repair & refurb service. Their clients only have their vehicle out of action for one day.



**EMAIL:** [info@isothane.com](mailto:info@isothane.com) or visit our website [www.isothane.com](http://www.isothane.com)  
**PHONE:** +44 (0) 1254 872555